



SERVICE BULLETIN

No. ²⁵⁵

Piper Aircraft Corporation

F.A.A. DOA EA-1 Approved

Lock Haven, Pennsylvania, U.S.A.
August 9, 1967 M

<u>Subject:</u>	Modification of Emergency Exit Window Mechanism
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2, 31-4, 31-5, 31-6, 31-9 to 31-33 incl., 31-35 to 31-59 incl.
<u>Compliance Date:</u>	Prior to but not later than next 50 hours of operation
<u>Reason For Bulletin:</u>	Improve the latching mechanism of the emergency exit window
<u>Material Required:</u>	Emergency Exit Window Mechanism Modification Kit 757 159
<u>Installation Instructions:</u>	Contained in Kit 757 159
<u>Availability of Parts:</u>	Piper Dealer
<u>Warranty Parts Allowed:</u>	Emergency Exit Window Mechanism Modification Kit 757 159
<u>Warranty Labor Allowed:</u>	Eight (8) hours
<u>Expiration Date of Warranty:</u>	January 31, 1968
