



SERVICE No. 258 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

F.A.A. DOA EA-1 Approved

November 1, 1967 M

<u>Subject:</u>	Alternate Air Box Assembly
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2 to 31-82 incl.
<u>Compliance Date:</u>	Prior to but not later than next 100 hours of operation
<u>Reason For Bulletin:</u>	To improve the Alternate Air Door Spring Attachments.
<u>Material Required:</u>	Alternate Air Door Spring Attachment Modification Kit 757 189
<u>Installation Instructions:</u>	Contained in Alternate Air Door Spring Attachment Modification Kit 757 189
<u>Availability of Parts:</u>	Piper Dealer
<u>Warranty Parts Allowed:</u>	Alternate Air Door Spring Attachment Modification Kit 757 189
<u>Warranty Labor Allowed:</u>	Two (2) Hours
<u>Expiration Date of Warranty:</u>	May 31, 1968
<u>Disposition of Replaced Parts:</u>	Comply with Warranty and Credit Claim Procedures

NOTE

Compliance cards have been furnished to each distributor and must be returned with the Warranty and Credit Claim to Piper Aircraft Corporation as soon as this bulletin is completed.

Date _____

COMPLIANCE WITH SERVICE BULLETIN NO. 258 HAS BEEN
COMPLIED WITH ON PA-31 NAVAJO, SERIAL NO. _____.

Distributor