



# SERVICE BULLETIN

No. 265

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"


February 5, 1968

---

<u>Subject:</u>	Wing Fillet, Louvered Access Plates
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2 to 31-100 incl.
<u>Compliance Date:</u>	Prior to but not later than the next 100 hours of operation
<u>Reason for Bulletin:</u>	To advise that a louvered access plate, part number 43004-00, must be installed on the lower rear surface of each wing root fillet. It has been reported that non-louvered access plates may have been installed in the wing fillets. All PA-31 aircraft should be inspected to insure that the correct plates are installed.
<u>Material Required:</u>	Part number 43004-00 should be ordered if louvered plates are not installed. (See sketch on reverse side of this bulletin for more descriptive information.)
<u>Warranty Parts Allowed:</u>	Part number 43004-00 (as required)
<u>Expiration Date of Warranty:</u>	August 31, 1968
<u>Disposition of Replaced Parts:</u>	Comply with Warranty and Credit Claim procedures

(over)

---



***SERVICE BULLETIN 265***