



SERVICE No. 544 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"Modification DOA EA-1 Approved"

March 8, 1977

M

Subject:

Airspeed Placard Installation

Models Affected:

Serial Numbers Affected:

PA-31-325 Navajo.....31-7400990, 31-7512006 to 31-7612110 Inclusive

Compliance Time: Immediately upon receipt of related material (reference Material Required, below); not to exceed the next fifty (50) hours of operation.

Purpose: To provide material and instructions to add an airspeed placard adjacent to the Airspeed Indicator referring to V_{NO} (upper limit of green arc) operation above 21,000 feet. This placard is shown in its proper location on the illustration on reverse side.

A corresponding Pilot's Operating Manual revision is also provided with the placard (reference Material Required, below).

Instructions: Contained in Airspeed Placard Installation Kit, Piper Part No. 761 125.

Material Required: One each per aircraft (PA-31-325 only) Airspeed Placard Installation Kit; Piper Part No. 761 125; contains required placard and related Pilot's Operating Manual revision.

Availability of Parts: Your Piper Field Service Facility.


Effectivity Date: This Service Bulletin is effective upon receipt.

Summary: Please contact your Piper Field Service Facility to make arrangements for compliance with the provisions of this Service Release in accordance with Compliance Time, above. Required placard installation kit specified above is provided no charge through your Piper Field Service Facility; placard installation time is negligible.

over

New Airspeed Placard 80486-02
(Locate as shown)

Existing Airspeed Placard



Existing Speed Control Placard