

SERVICE



LETTER

Service Letter No. 498

March 1, 1968

<u>Subject:</u>	Nose Gear Idler Link Assembly
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2 to 31-85 incl., 31-87 to 31-91 incl., 31-93, 31-103
<u>Compliance Date:</u>	Prior to but not later than the next 100 hours of operation
<u>Reason for Letter:</u>	A new part number has been assigned to the subject assembly. Kit No. 760 170 (Nose Gear Idler Link Identification) contains a metal identification plate which denotes this change.
<u>Material Required:</u>	Kit No. 760 170 (Nose Gear Idler Link Identification)
<u>Installation Instructions:</u>	Contained in Kit No. 760 170
<u>Availability of Parts:</u>	Piper Dealer
<u>Warranty Parts Allowed:</u>	Kit No. 760 170
<u>Expiration Date of Warranty:</u>	September 30, 1968