



SERVICE LETTER

No. 660

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

July 6, 1973 M

Subject:

Revised Alternator Ground Wire Installation

Models Affected:

PA-31 Navajo
PA-31-350 Navajo Chieftain

Serial Numbers Affected:

31-7300842 to 31-7300957 incl.
31-5001 to 31-5004 incl., 31-7305005 to 31-7305068 incl.

Compliance Time:

Within the next 100 hours of operation.

Purpose:

To provide material and instructions to improve the alternator ground wire attachment on left and right alternators on the above referenced aircraft.

Instructions:

Contained in Alternator Ground Wire Installation Kit, Piper Part No. 760 778.

Material Required:

One each per aircraft Alternator Ground Wire Installation Kit, Piper Part No. 760 778.

Availability of Parts:

Your Piper Dealer.

Effectivity Date:

This Service Letter is effective July 20, 1973.

Summary:

Please contact your Piper Dealer to make arrangements for compliance with this Service Letter in accordance with the provisions of Compliance Time, above. Material required for this modification is available free of charge through your Piper Dealer, providing the modification is accomplished by a Piper Dealer. Time required for this modification is negligible.

A Service Publication Compliance form is enclosed with each copy of this Service Letter mailed to affected owners/operators of record. Following compliance with this Service Letter, please fill out the form according to the instructions on the reverse side of the form bottom copy and leave the form with your Piper Dealer.