



SERVICE LETTER

No. 821

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

March 7, 1978

M

Subject: Right Engine Cowl Louver Installation Kit

Models Affected: Serial Numbers Affected:

PA-31-350 Navajo Chieftain..... 31-5001 to 31-7852015 inclusive

Compliance Time: At owner/operator's discretion.

Purpose: This Service Release announces availability of material and instructions to install engine cowl louvers on the right engine to provide additional cooling air flow through the right engine compartment to reduce right engine operating temperatures.

Instructions: Contained in Piper Kit No. 763 802, Right Engine Cowl Louver Installation.

Material Required: One (1) each per aircraft, Piper Kit No. 763 802 Right Engine Cowl Louver Installation at suggested list price \$28.95A.

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This Service Release is effective upon receipt.

Summary: Please contact your Piper Field Service Facility to make arrangements for installation of the above described product refinement modification if your Chieftain is subject to relatively high right engine operating temperatures. Installation time can be minimized by coordinating this modification with a regularly scheduled inspection/maintenance interval.