



SERVICE LETTER

No. 875

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

FAA Approved

May 11, 1981

M

Subject:

Engine Front Baffle Replacement

Models Affected:

PA-31/31-325 Navajo
PA-31-350 Chieftain

Serial Numbers Affected:

31-2 through 31-8012045
31-5001 through 31-8052085

Compliance Time:

At owner's/operator's discretion; recommended
at next regularly scheduled maintenance event,

Purpose:

Current production aircraft are equipped with improved front engine cooling baffles. This Service Release announces the availability of a kit to allow the above-listed aircraft to install these improved baffles.

Instructions:

All Materials and Instructions are included in Piper Part No. 764 093, Engine Front Baffle Replacement Kit.

Material Required:

One (1) each per engine, Engine Front Baffle Replacement Kit, Piper Part No. 764 093.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to arrange for compliance with this Service Release.