



SERVICE LETTER

No. 868

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

March 26, 1979 M

Subject:

Wing Flap Selector Switch Positive
Detent Kit Installation

Models Affected:

PA-31T1 Cheyenne I
PA-31T Cheyenne II

Serial Numbers Affected:

31T-7804001 through 31T-7804011
31T-7420002 through 31T-7820066 and
31T-7820068 through 31T-7820092

Compliance Time:

Recommended at the next scheduled inspection.

Purpose:

This modification of the Wing Flap Selector Switch installation to include a positive detent will lessen the possibility of inadvertently over running the "APPROACH" position (Reference Piper Service Bulletin No. 588) and the subsequent necessity of reprogramming the flaps.

This Service Letter announces the availability of Piper Kit number 763 894, Flap Selector Switch Positive Detent Installation.

Instructions:

Installation instructions are included with Kit Number 763 894.

Material Required:

One (1) each per aircraft, Piper Kit Number 763 894, Flap Selector Switch Positive Detent Installation at a suggested list price of \$7.00 A each.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Release is effective upon receipt.

(over)

Summary:

Please make arrangements with your Piper Field Service Facility to comply with the provisions of this Service Letter at your convenience. It is recommended that the modification be scheduled to coincide with a regularly scheduled inspection event to avoid unnecessary down time. Reimbursement for Material is available for all affected aircraft, and reimbursement for both material and labor (up to a maximum of two (2) hours per aircraft) is available for aircraft in their warranty period. Comply with the respective material/labor credit application procedure of your Piper Field Service Facility.

This offer remains in effect for a period of time not to exceed 180 days from the date of this service release.