

The Piper logo consists of the word "PIPER" in a bold, sans-serif font, enclosed within a dark rectangular box with a diagonal line running from the top-left to the bottom-right.

**Customer Services**

# SERVICE BULLETIN

**No. 431**

Piper Aircraft Corporation

"FAA DOA EA-1 Approved"

Lock Haven, Pennsylvania, U.S.A.

August 5, 1974

---

Subject: Electric Razor Outlet Placard

Models Affected: Serial Numbers Affected:

(Only aircraft listed below incorporating right rear divider panel mounted razor outlets are affected.)

PA-31-350 Navajo Chieftain 31-5001 to 31-7405455 incl.

Compliance Time: Within the next 50 hours of operation.

Purpose: To provide material and instructions to placard the right rear divider panel razor outlet with placards reading as follows: "110 VOLT RAZOR ONLY" and "SWITCH OFF WHEN NOT IN USE".

Instructions:

1. Install placard part number SK-2360 ("110 VOLT RAZOR ONLY") .25 inch below the razor outlet plug.
2. Install placard part number SK-2361 ("SWITCH OFF WHEN NOT IN USE") .31 inch below the razor outlet plug on/off switch.
3. Make appropriate log book entry.

Material Required: One (1) each of the following placards, applicable to the above referenced aircraft with factory installed cabin right rear divider panel razor outlets; part number SK-2360 ("110 VOLT RAZOR ONLY") and part number SK-2361 ("SWITCH OFF WHEN NOT IN USE").

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This service letter is effective upon receipt.

Summary: Please contact your Piper Field Service Facility to make arrangements for compliance with the provisions of this service release in accordance with Compliance Time above.

Material required for this modification is available free of charge through your Piper Field Service Facility.

---