



SERVICE No. 270 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"

February 23, 1968

<u>Subject:</u>	Elevator Tip De-Icer Boot Installation
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2 to 31-20 incl., 31-22 to 31-30 incl., 31-33 to 31-43 incl., 31-45 to 31-106 incl., 31-108, 31-111 to 31-114 incl., 31-116, 31-118 to 31-120 incl., 31-122 to 31-124 incl., 31-126 to 31-129 incl., 31-131 to 31-133 incl., 31-135 to 31-148 incl.
<u>Compliance Date:</u>	Prior to but not later than the next 100 hours of operation
<u>Reason for Bulletin:</u>	To provide material and instructions for the installation of elevator tip de-icing boots.
<u>Material Required:</u>	Elevator Tip De-Icer Boot Kit 757 200
<u>Installation Instructions:</u>	Contained in Kit 757 200
<u>Availability of Parts:</u>	Piper Dealer
<u>Warranty Parts Allowed:</u>	Elevator Tip De-Icer Boot Kit 757 200
<u>Warranty Labor Allowed:</u>	Two (2) hours
<u>Expiration Date of Warranty:</u>	August 31, 1968
