



SERVICE BULLETIN

No. 517

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"Modification DOA EA-1 Approved"

October 5, 1976 M

Subject: Engine Oil Temperature Gauge Placard Installation.

Models Affected: Serial Numbers Affected:

PA-31T Cheyenne 31T-7620012 to 31T-7620050 Inclusive.

Compliance Time:

At the next scheduled Continuous Maintenance Event, not to exceed the next 100 hours of operation.

Purpose:

The subject oil temperature gauges in the above referenced aircraft are not identified as to function, that is "OIL TEMP °C": This lack of identification can cause difficulty in locating the gauge.

This service release provides material and instructions to apply a gauge identification placard to the glass face of the engine oil temperature gauges.

Instructions:

1. Carefully trim placards along borders;
2. Remove backing (placard is self-adhering);
3. Locate and apply placard to the instrument glass face, centered between the "0° - 100°" markings at the six o'clock position (on the glass face). Be sure glass is clean before applying placard.
4. Insure proper entry is made in aircraft log book.

Material Required:

Two (2) each per aircraft Placard, Engine Oil Temperature Piper Part Number 757 487.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This service release is effective upon receipt.

over

Summary:

Placard application (described above) may be accomplished by the owner/operator; appropriate placards are available free of charge through your Piper Field Service Facility.